

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Tuesday, February 19, 2013

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	35.29	38.56
C3.2 Water Gauge	36.18	38.58
E0.5 Water Gauge	36.87	37.44
E2 Boat Launch	36.70	40.76
E4 Boat Launch	34.66	35.64

Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit



1. C0.4 Boat launch river conditions observed.



2. C0.4 Boat launch river conditions observed.



3. MP5.75 Ceresco Dam impoundment river conditions observed.



4. MP5.63 Ceresco Dam impoundment river conditions observed.





5. Ceresco Dam impoundment river conditions observed.



6. C3.2 Pole Barn observed core logging.



7. C3.2 Observed river conditions.



8. MP15.25 South Mill Pond river icing conditions observed.





9. MP15.75 North Mill Pond river icing conditions observed.



10. MP21.5 River conditions observed.





11. MP26.25 RDB observed the RI crew.



12. MP26.0 Sediment trap river conditions.





**13. MP27.0 Shady Bend Campground river conditions observed.**



**14. E2 Boat launch observed river conditions.**



**15. Morrow Lake water conditions.**



**16. Morrow Lake Delta Neck river conditions observed.**





17. Morrow Lake Delta river conditions observed.



18. Morrow Lake Delta river conditions observed.





**19. MP10.5 Sediment trap icing conditions observed.**



**20. MP10.4 Sediment trap icing conditions observed.**